



Westex® FR7A Clean and Care Instructions

100% Cotton, Clean garment thoroughly, Detergent only, Wash up to 165° (74°C), No chlorine bleach or peroxide either separately or in detergents, No softeners or starch, Failure to launder properly could adversely affect the flame resistance of the fabric, complete cleaning guide can be found at Westex.com. Flame resistance guaranteed for 25 industrial or 50 home launderings.

100% Algodón, Limpiar la prenda a fondo, Solo detergente, Lavar hasta 165° (74° C), Sin blanqueador de cloro ni peróxido, ya sea por separado o en detergentes, Sin suavizantes ni almidón, No lavar correctamente podría afectar adversamente la resistencia a las llamas del tela, la guía de limpieza completa se puede encontrar en Westex.com. Resistencia a la llama garantizada para la vida de la prenda.

